



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3984-030
Job Sheet 199883



Part No: D3984-030

Job Qty: 60 pcs

Part Name: Rubber Extrusion, X-tube, 3"



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/4/19

Job Tracking No:

Due Date: 9/27/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV A

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Packaging 1 - Pick Kit	60 pcs		9/27/19	0.00	0.00	Packaging 1 - 1		
							Packaging 1 - 2		
							Packaging 1 - 3		
							Packaging 1 - 4		
							Packaging 1 - 5		
							Packaging 1 - 6		
							Packaging 1 - 7		
							Packaging 1 - 8		
							Packaging 1 - 9		
							Packaging 1 - 10		
							Packaging 1 - 11		
							Packaging 1 - 12		
							Packaging 1 - 13		
							Packaging 1 - 14		
							Packaging 1 - 15		
							Packaging 1 - 16		
							Packaging 1 - 17		
							Packaging 1 - 18		
							Packaging 1 - 19		
							Packaging 1 - 20		
							Packaging 1 - 21		
							Packaging 1 - 22		
							Packaging 1 - 23		
							Packaging 1 - 24		
							Packaging 1 - 25		
							Packaging 1 - 26		
							Packaging 1 - 27		
							Packaging 1 - 28		
							Packaging 1 - 29		
							Packaging 1 - 30		
							Packaging 1 - 31		

SEP 13 2019

Plex 9/4/19 9:07 AM Dart.lajeunesse.marie

				Packaging 1 - 32	
				Packaging 1 - 33	
				Packaging 1 - 34	
				Packaging 1 - 35	
				Packaging 1 - 36	
105	Small Fab - 2 - B4B	60 pcs	9/27/19	0.00 1.50	Small Fab - 1 - B4B
					Small Fab - 2 - B4B
					Small Fab - 3 - B4B
					Small Fab - 4 - B4B
					Small Fab - 5 - B4B
					Small Fab - 6 - B4B
					Small Fab - 7 - B4B
					Small Fab - 8 - B4B
110	QC 5	60 pcs	9/27/19	0.00 0.00	QC 5 - 10
					QC 5 - 12
					QC 5 - 17
					QC 5 - 18
					QC 5 - 19
					QC 5 - 22
					QC 5 - 24
					QC 5 - 3
					QC 5 - 43
					QC 5 - 49
					QC 5 - 51
					QC 5 - 58
					QC 5 - 68
					QC 5 - 9
					QC 5 - 50
					QC 5 - 30
					QC 5 - 40
					QC 5 - 61
					QC 5 - 81
120	Packaging 3-1 - Stock - B4B	60 pcs ✓	9/27/19	0.00 0.00	Packaging 3 - 1 - B4B
					Packaging 3 - 2 - B4B
					Packaging 3 - 3 - B4B ✓
					Packaging 3 - 4 - B4B
					Packaging 3 - 5 - B4B
					Packaging 3 - 6 - B4B
					Packaging 3 - 7 - B4B
					Packaging 3 - 8 - B4B
					Packaging 3 - 9 - B4B
					Packaging 3 - 10 - B4B
					Packaging 3 - 11 - B4B
					Packaging 3 - 12 - B4B
					Packaging 3 - 13 - B4B
					Packaging 3 - 14 - B4B
					Packaging 3 - 15 - B4B
					Packaging 3 - 16 - B4B
					Packaging 3 - 17 - B4B
					Packaging 3 - 18 - B4B
					Packaging 3 - 19 - B4B
					Packaging 3 - 20 - B4B
					Packaging 3 - 21 - B4B
					Packaging 3 - 22 - B4B
					Packaging 3 - 23 - B4B
					Packaging 3 - 24 - B4B
					Packaging 3 - 25 - B4B
					Packaging 3 - 26 - B4B
					Packaging 3 - 27 - B4B

SEP 13 2019

DAS

SEP 13 2019

40

9-89

Mon 9-16-2019

Rosales, Oscar

ST064

				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
130 QC 21 - SA	60 pcs ✓	9/27/19	0.00 0.00	QC 21 - SA - 21 ✓	ST 064
closed wo only JK				QC 21 - SA - 70	SEP 16 2019
				QC 21 - SA - 53	DAS 70 9-89
Part Op 100 - (Pick Kit) cut per drwg Descriptions: 105 - (Small Fab) 110 - (QC5- Inspect part completeness to step on W/O) 120 - (Identify as per dwg & Stock Location: _____) 130 - (QC21- Final Inspection - Work Order Release)					
Job BOM					
Part / Item	Component Name	Quantity	Operation	Container	
D3984	Rubber Extrusion, Crosstube (\$ Per Foot)	54/13 15 pcs (.25 ea)	100-Packaging 1 - Pick Kit	S/35084.	
Job Allocations					
Operation	Component Part	Required	Inventory	Allocated	
100-Packaging 1 - Pick Kit	D3984	15	113	0	
Part Specifications					
Specifications could not be found.					

Plex 9/4/19 9:07 AM Dart.lajeunesse.marie

Entered:

Date:

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No.

Route update only



Job: _____ Part No. _____		DISPOSITION Rework ☐ ☐ Scrap ☐ ☐ Use-as-is ☐ ☐		DEPARTMENT/PROCESS Skid-tube ☐ ☐ ☐ ☐ Machining ☐ ☐ ☐ ☐ Large Fab ☐ ☐ ☐ ☐ Cross tube ☐ ☐ ☐ ☐ Small Fab ☐ ☐ ☐ ☐ Finishing ☐ ☐ ☐ ☐ Eng. (Non-AW) ☐ ☐ ☐ ☐ Prod. Eng. Coord. ☐ ☐ ☐ ☐ Rec/Store/Packaging ☐ ☐ ☐ ☐ Engineering ☐ ☐ ☐ ☐ Water Jet ☐ ☐ ☐ ☐ Supplier ☐ ☐ ☐ ☐ Quality ☐ ☐ ☐ ☐		Date : _____ Sequence #: _____ QTY Affected : _____		MRB (QS1042)																									
Description Work Order Deviation		Disposition		Completed By																													
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY <table border="1"> <tr> <td>Pressure/Forced</td> <td>Contamination</td> <td>Power Loss/Surge</td> <td>Positioned Wrong</td> </tr> <tr> <td>Bending</td> <td>Misaligned/off center</td> <td>Folio/Program</td> <td>Outside Tolerance</td> </tr> <tr> <td>Crushing</td> <td>BOM/Route</td> <td>Grain Direction</td> <td>Drawing</td> </tr> <tr> <td>Cracks</td> <td>Broken/Damage/Defect</td> <td>Weld</td> <td>Finish</td> </tr> <tr> <td>Crimp/Kink/Ripple/Wave/Twist</td> <td>Incomplete/Unclear Instructions</td> <td>Wrong Stock Pulled</td> <td>Part Lost/Missing</td> </tr> <tr> <td>Marks/Chatter</td> <td>Drill Holes</td> <td>Out of Sequence</td> <td>Misread</td> </tr> <tr> <td>Mislabeled</td> <td>Fit/Function</td> <td>Off-set/Set-up</td> <td></td> </tr> </table>				Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong	Bending	Misaligned/off center	Folio/Program	Outside Tolerance	Crushing	BOM/Route	Grain Direction	Drawing	Cracks	Broken/Damage/Defect	Weld	Finish	Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing	Marks/Chatter	Drill Holes	Out of Sequence	Misread	Mislabeled	Fit/Function	Off-set/Set-up	
Pressure/Forced	Contamination	Power Loss/Surge	Positioned Wrong																														
Bending	Misaligned/off center	Folio/Program	Outside Tolerance																														
Crushing	BOM/Route	Grain Direction	Drawing																														
Cracks	Broken/Damage/Defect	Weld	Finish																														
Crimp/Kink/Ripple/Wave/Twist	Incomplete/Unclear Instructions	Wrong Stock Pulled	Part Lost/Missing																														
Marks/Chatter	Drill Holes	Out of Sequence	Misread																														
Mislabeled	Fit/Function	Off-set/Set-up																															
Other/Details:		Lead hand / Supervisor QC / QA Coordinator																															